
Uncertainty component	Standard uncertainty/%
Radiometric calibration	0.8
Lamp stability	0.2
Non-linearity and stray light	0.4
Stability	0.8
Temperature dependence	0.1
Measurement noise	0.2
Wavelength shift	0.1
Combined uncertainty ($k = 1$)	1.24
Expanded measurement uncertainty ($k = 2$)	2.5
